





FIG. 2



6/24

FIG. 6



9/24

FIG. 9





FIG. 13



22/24

FIG. 22A

(PRIOR ART)






FIG. 22B

(PRIOR ART)



23/24

FIG. 23
(PRIOR ART)



24/24

FIG. 24A

(PRIOR ART)

DRIVE CURRENT OF FIRST
SENSOR PROBE



FIG. 24B

(PRIOR ART)

DRIVE CURRENT OF
SECOND SENSOR PROBE



FIG. 24C

(PRIOR ART)

GROUND CURRENT




FIG. 24D

(PRIOR ART)

GROUND CURRENT AMPLITUDE VALUE (RELATIVE VALUE)




FIG. 24E

(PRIOR ART)

MEASUREMENT VALUE
OF FIRST SENSOR

MEASUREMENT VALUE
TRUE VALUE

LARGE INTERVAL

ERROR




FIG. 24F

(PRIOR ART)

MEASUREMENT VALUE
OF SECOND SENSOR

MEASUREMENT VALUE
TRUE VALUE

LARGE INTERVAL

ERROR

